AIRGAINCONNECT® FLEET™ 5G VEHICLE GATEWAY

Version 13.01.02.0014
Software Release Notes
January 30, 2026

Airgain, Inc provides this documentation in support of its products for the internal use of its current and prospective customers. The publication of this document does not create any other right or license in any party to use and content in or referred to in this document and any modification or redistribution of this document is not permitted.

While efforts are made to ensure accuracy, typographical and other errors may exist in this document. Airgain, Inc reserves the right to modify or discontinue its products and to modify this and any other product documentation at any time.

All Airgain, Inc products are sold subject to its published Terms and Conditions, subject to any separate terms agreed with its customers. No warranty of any type is extended by publication of this documentation, including, but not limited to, implied warranties or merchantability, fitness for a particular purpose and non-infringement.

Table of Contents

1   Scope of Release

Details for release of new AirgainConnect Fleet (AC-Fleet) firmware version v13.01.02.0014.

2 Release Contents

|	
Build Date/Time	2025/11/21
Build Version	v13.01.02.0014
Cellular Module Version	A0R.001062-7903-000100
Wi-Fi Driver Version	5.2.0.220S.089
MCU FW Version	1.1.09
Released Files	Firmware: v13.01.02.0014.bin
	Notes: Airgain_AC-Fleet Release Notes_v13.01.02.0014.pdf

3 Fixes and Features Included

Fixes and features included in v13.01.02.0014:

1. Updated to achieve optimal performance on T-Mobile's T-Priority network.
2. Fixed an issue where AC-Fleet gives the following error when attempting to upgrade firmware using a 15V power supply.

Flash image aborted

Device will only flash image when vehicle battery is 25V or above. Please fully charge vehicle battery first and try again.

Cancel

3. Added a notification for when the system recovers from a secure boot failure.

4 Upgrade

Use the **Backup / Flash Firmware** menu to pull the latest firmware from AC-Cloud.



| Upgrade to latest version | Upgrade Now |

You can also push firmware updates from AC-Cloud per the following instructions:

1. Ensure the device is subscribed and has a good internet connection where the status shows "Online".

2. Log into your AC-Cloud organization account and verify the latest firmware is available under **Groups** > **Firmware**.
3. Navigate to **Groups** > **Groups** and click **Add** to create a group.

4. Assign the group a name and click **Edit** to add devices to that group.

5. Select the device(s) to include in the group and click on **Save**.

6. Select the desired firmware version under the **Firmware** dropdown menu.
7. Under **Schedule FW/Config Update**, select when the update is to take place.

Note: There is a known bug where **Up on next bootup** won't initiate without first entering standby mode (ignition turned off while connected to power). If the ignition line is also connected to power, then select **Immediate** update.

8. Once the group is defined, click **Add** to create the group and schedule the firmware update.